

# Atacama

**WHAT HI-FI?**  
AWARDS 2014

Accessories  
Best speaker stand  
Atacama Moseco 6

## MOSECO ASSEMBLY INSTRUCTIONS

AWARDED BEST SPEAKER STAND-EVERY YEAR

2014 TO 2024

**WHAT HI-FI?**  
\*\*\*\*\*  
AWARDS 2024

BEST SPEAKER  
STANDS  
ATACAMA  
MOSECO 6



### Assembly kit

- 4 x M8 pan head Bolts
- 4 x M8 counter sink Bolts
- 8 x M8 spikes
- 8 x M8 lock nuts
- 8 x bumpers
- 2 x badges

NOTE:- BAMBOO PANEL  
SHAPE MAY DIFFER  
DEPENDING ON  
VERSION PURCHASED

Bolt the columns to the bases using the M8 pan heads. Ensure the cable management holes are facing to the rear of the bases.

Note- **Threading the speaker cable through the cable management holes is easier if done before assembly!**

If you have purchased Atabite filler separately, 1/2 to 2/3rds fill the front column of each stand.

Bolt the top plates to the columns using the M8 counter sinks. Line up tops with the bases before tightening up.

Fit the lock nuts onto the carpet spikes and screw into the base.

Locking off once stands are level.

Fit the bumper pads to the top plates.

## MOSECO UPGRADE OPTIONS.

### Congratulations!

You have chosen a GREAT pair of speaker stands.

Here are the upgrades to make them even better!



### Large Top Plate Pack

A 160mm (W) x 220mm (D) Top plate upgrade pack is available.



### Isolation Gel Pads

Improves speaker cabinet dampening.



### Atabites

Increases mass, reduces ringing.



### Mass Loading Plate Pack

Increases mass, improves stability.



### Spike shoes

Protects delicate floor coverings.

Visit [www.atacama-audio.co.uk](http://www.atacama-audio.co.uk) for more details.

## PLEASE NOTE

**Natural Variations in Bamboo:** Please note that bamboo is a natural material, and as such, there may be variations in colour, texture, and grain between individual stands. These differences are normal and do not affect product performance. **Colour Matching with Atacama Bamboo Racks:** When matching these stands with an Atacama Bamboo hifi or AV rack, please be aware that slight colour differences may occur due to variations in bamboo batches and production timing.